

**THE CONTENTS OF THIS DOCUMENT
ARE THE HIGHEST QUALITY AVAILABLE**

INITIAL QV DATE 3/2/00

Appendix B
Photographs

Appendix B


Photographs

Photographs in addition to those included here are available in the project files. A notation tab in the lower left or center of each photograph describes the subject matter.

St. J. Basil's Church


Spring 1996

96-174-18-3




CD960200

SL-1 BURIAL GROUNDS
CLEAR & GRUB ACTIVITIES
AUGUST 1996




CD960407

SL-1 Burial Ground
Excavated Areas
September 5, 1996



CD960406


SL-1 Burial Ground
Consolidated Soil
September 5, 1996



SL-1 Burial Ground
Gravel Layer Installation

October 8, 1996


96-584-1-33A



SL-1 Burial Ground
Rip Rap Layer Installation

October 8, 1996


96-604-1-20A



SL-1 Burial Ground
Rip Rap Layer Installation


October 8, 1996

96-684-1-31A



CD970024

SL-1 Burial Ground
Fence and Monument Completion
January 6, 1997



CD971265

SL-1 Vegetation Status


June 18, 1997



BORAX-I Burial Ground


Spring 1996

96-174-17-5




CD960236

WORAX-1
CONTAMINATED SOIL
EXCAVATION
AUGUST 1996



CD960239


BORAX-I
CONSOLIDATED SOIL
AUGUST 1996



BORAX-I Burial Ground
Rip Rap Layer Installation

November 5, 1996


105-180-1-37



CD970018

BORAX-I Burial Ground
Fence and Monument Completion

January 6, 1997



CD971330

BORAX-1, Vegetation Status

June 23, 1997